4 Crude Moan List

		4 Crude Moan List 9/21/09
	6/16/09	V-1190 top sight glass, top lead 2" gate valve leaks by & packing gland cocked – maximo # 285294 (Ryan Angen, Mike Dotson)
	2/6/09	(Dave Shin) replace two 4" block valves, L-52 at C1180. U/S hard to turn, D/S leaks by.
	1/23/09	Fuel gas supply to compressors for clean up plugged after leaving V1196. (OTR)
	1/14/09	E1111 – ABCR (tube side) bypass valve stuck open. 10" Gate Valve.
	1/14/09	T1108 block valve to sample cooler broken at stem. OTR
	1/14/09	E1169 internal leak CW leaking into compressor suction line. (OTR)
	1/8/09	F1100A TI 077 F1100B TI182, 244, 186, 231, 247, 167,176, 250 F1160 TI627, 005, 592, 593, 089, 693, 607
	1/8/09	V1102 install check valve on tri line return to crude feed line. (we are getting crude out of the desalter sampler instead of desalter sample at times)
	1/8/09	P1178's put duplex strainer on suction lines. O/F system plugged.
	12/16/08	W/R $\#$ 271140 rotate 1 $\frac{1}{2}$ " welded valve . (Safety request, PSSR) condensate system in front of MP1179
	8/18/07	8" Gate Valve V1160 Off gas line. Needs to be replaced. Very difficult to turn.
· 4 .	8/18/07	1/2" root valve needs to be replaced, V1160 off gas FI, bad seat.
	10/23/07	Bad 34" valve on 150# steam supply line to W/D stations – Street side F1100A, can't use W/D stations per Gordy.
	10/08	E1107 Crude line inlet Block valve 16" packing was shot by